

**To:** Restaino, Mark[restaino.mark@epa.gov]  
**From:** Scott Hansen  
**Sent:** Mon 5/19/2014 6:08:54 PM  
**Subject:** RE: Moring Star Market

...

»»  
Hello Mark,

The e-mail sent on 4/15/14 shows a vacuum line on the STP that goes to manifold (not sure how to verify, without digging up) creating a vacuum between the two compartments.

The ATG records basically show similar levels on both sides. Maybe could ask Rich if they just fill into one tank, not sure that information would mean much.

Third party certification requires 50 % needed in tanks, and that they have not been tested/certified on manifolded tanks.

Take Care,

Scott Hansen

**From:** Restaino, Mark [mailto:restaino.mark@epa.gov]  
**Sent:** Monday, May 19, 2014 10:43 AM  
**To:** Scott Hansen  
**Subject:** Moring Star Market

Scott,

I am planning to issue the Morning Star Market an Information Request. I was trying to remember what we discussed. If I remember correctly there were two issues still remaining at the site, all having to do with the Auto-Stik Jr. The first issue is to figure out how the USTs are manifolded and the second is ensuring that the USTs are 50% full when conducting a test. Do you recall if there was anything else?

Thanks.

-Mark